

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|--|
| 00 | 22.07.2008 | Orijinal / Original |
| 01 | 02.01.2009 | <p>P/Ns : 3000-46-2, 3000-46-5, 3000-46-7, 3000-46-12, 3000-46-13, 3000-46-14, 3000-46-15, 3000-46-16, 3000-46-18, 3000-46-19, 3000-46-20, 3000-46-21, 3000-46-22, 3000-46-23, 3000-46-24, 3000-46-27, 3000-46-28, 3000-46-29, 3000-46-32, 3000-46-41, 3000-46-42, 3000-46-43, 3000-87-2, 3000-462-1, 3000-608-1, 3100-3-218, 3100-81-1, 3100-101-1, 3100-101-3, 3100-101-4, 3100-101-6, 3100-119-2, 3100-119-3, 3100-160-16, 3100-190-12, 3100-241-1, 3100-250-1, 3100-250-2, 3100-250-3, 3100-250-4, 3100-250-5, 3100-250-6, 3100-262-1, 3100-262-2, 3100-262-3, 3100-262-4, 3100-292-1, 3800-32-3, Thermal Switch Assembly of Honeywell – Elmwood Sensors Inc. are added.</p> <p>P/N: 641121-1, Overheat Zone Duct Switch of Honeywell is added.</p> <p>P/N: 641172-1, Pack Discharge Overhead Switch of Garrett – Airesearch is added.</p> <p>P/Ns: 69-68010-1, 69-68010-3, 69-68010-6, 69-68010-8, 69-68010-10, 69-68010-11, Telephone Printed Circuit Assy of Boeing are added.</p> <p>P/Ns: 65-62238-1, 65-62238-2, Cargo Door Latch Actuator Assembly of Boeing are added.</p> <p>P/N: S-9100, Life Preserver Model AV-10, TYPE A of Switlik Parachute Company is added.</p> <p>P/N: S-10000-(), Life Preserver Model ILV-20 of Switlik Parachute Company is added.</p> <p>P/N: S-1200, Life Preserver Model AV-2A,TYPE A of Switlik Parachute Company is added.</p> <p>P/Ns: S-3100, S-3100-1, Life Preserver Model AV-12A,TYPE A of Switlik Parachute Company is added.</p> <p>P/N: S-12000-(), Life Vest AV-40 of Switlik Parachute Company is added.</p> <p>P/N: S-21000-(), Life Preserver Model AV-35 of Switlik Parachute Company is added.</p> <p>P/N: S-11000-(), Life Preserver Model AV-35 of Switlik Parachute Company is added.</p> <p>P/N: S-51XXX-(), Life Preserver Model AV-35 of Switlik Parachute Company is added.</p> <p>P/N: 968214-X, Pressure Relief Valve Assembly of Allied-Signal Aerospace Company is added.</p> <p>P/N: 69-62790-2, Leading Edge Flap and Slat Position Indicator Unit Assembly of Boeing is added.</p> |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|---|
| 01 | 02.01.2009 | <p>P/N: 90G118-2, Pressure Switch of Custom Component Switches, Inc is added.P/N: 3-1531, 3-1531-1, 3-1531-2, 3-1531-3, Nose Landing Gear Wheel Assembly of Goodrich are added.</p> <p>P/N: 617786-2 Series 1 and 2, Temperature Control Sensor of Honeywell are added.</p> <p>P/N: CG7P0, CG7G0, CG7G0-S, CG7G0-10, CG7G0-11, Smoke Detector of Cerberus Sa are added.</p> <p>P/N: LM-321-SA15, Aircraft Engine Mounting System of Lord Aerospace Products is added.</p> <p>P/N: LM-321-118, LM-321-118H, Aircraft Engine Mounting System of Lord Corporation are added.</p> <p>P/N: LM-321-57, LM-321-58, Aircraft Engine Mounting System of Lord Corporation are added.</p> <p>P/Ns: 2607825-1, 2607825-2, Nose Wheel Assembly of Honeywell are added.</p> <p>P/N: 2609801-1 Main Wheel Assembly of Honeywell is added.</p> <p>P/Ns: 2606671-1, 2606671-2, 2606671-3 Main Wheel Assembly of Honeywell are added.</p> <p>P/N: 2612311-1 Main Wheel Assembly of Honeywell is added.</p> <p>P/Ns: 2606672-1, 2606672-2, 2606672-3, 2606672-4 Main Brake Assembly of Honeywell are added.</p> <p>P/N: 2612312-1 Main Brake Assembly of Honeywell is added.</p> <p>P/N: 21SN41-42, 21SN41-52, 21SN41-84 Pressure Switches of EATON are added. P/N: 1201, 12101 Aircraft Batteries of Saft are added.</p> <p>P/N: 23578, Aircraft Battery, Saft is added.</p> <p>P/N: 4608-1, Aircraft Battery, Saft is added.</p> <p>P/N: 4579, Nickel Cadmium Battery, Saft is added.</p> <p>P/N: 43B034LB03, Aircraft Battery, Saft is added.</p> <p>P/N: 3121-01, Emergency Light Supply Unit, Diehl is added.</p> <p>P/N: 60-1177-5, 60-1177-7, 60-1177-9 Battery Power Supply, Grimes Division are added.</p> <p>P/Ns: CG7GD1,CG7GE,CG7GF, CG7GF-10,CG7GFSG,CG7PD1,CG7PE,CG7PF,CG7PF-10 , Smoke Detector of Cerberus Sa are added.</p> |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|--|
| 2 | 12.03.2009 | <p>P/Ns: 20108, 20108-1, Aircraft Battery, Saft are added.</p> <p>P/Ns: 641109-1, 641109-2, 641109-3, 641109-4, 641109-5, Thermal Switch, Honeywell (Allied-Signal) are added.</p> <p>P/Ns: 23175, 23176, 2376, 2376-1, 2376-4, Cadmium Nickel Storage Battery, Saft are added.</p> <p>P/N: 2778-1, Aircraft Battery, Saft is added.</p> <p>P/N: 1152552-1, 40 AHR Battery, Honeywell is added.</p> <p>P/Ns: 5930645-1, 5930645-501, 5930645-503, 5930645-505, 5930645-507, 5930645-509, 5930645-511, SR09710029-11, SR09710029-13, SR09710029-3, SR09710029-5, SR09710029-7, SR09710029-9, Engine Nose Section Cowling Assembly, Boeing are added.</p> <p>P/Ns: 23491, 23491-3, Aircraft Battery, Saft are added.</p> <p>P/Ns: Marathon Micro Maintenance (M³)(Applicable to M³-28-1, M³X-33-1, M³-44-1, TM³-44-4, M³-44-7, M³-44-8, M³-44-9, M³-44-11, M³-44-15, M³-44-21, M³-44-22, M³-460L-1, M³-460L-1A, M³-54-1, M³-54-2, M³X-54-1, 20-60M³X100, M81757/15-1, M81757/15-2, M81757/15-3, M81757/16-1, M81757/18-1, 7-75M³120), Nickel Cadmium Aircraft Battery, Marathon Norco Aerospace are added.</p> <p>P/N: 17343-116-825F, Aircraft Overheat Detector, Fenwal Safety Systems is added.</p> <p>P/Ns: 915F213-3, 915F213-4, Bus Protection Panel, Hamilton Sunstrand are added.</p> <p>P/N: 572756-1, Thermal Switch, Allied Signal Aerospace – Los Angeles Division is added.</p> <p>P/Ns: 3937860-5001, 3937860-5002 3937860-5501, 3937860-5502, Main Landing Gear Retract Cylinder Gland Assembly, Douglas Aircraft Company are added.</p> <p>ELDEC, Boeing and Saft part numbers have been added to 4579 Aircraft Nickel Cadmium Battery, Saft.</p> <p>P/Ns: 286351006, 286351006-1, 286351007, 286351007-1, Wheel, Messier-Bugatti, are added.</p> <p>P/Ns: 286351005, 286351005-1, Wheel, Messier-Bugatti, are added.</p> <p>P/Ns: 286351004, 286351004-1, 286351004-2, Wheel, Messier-Bugatti, are added.</p> <p>P/Ns: C21928, C21928-1, 286351003, 286351003-1, 286351003-2, 286351003-3, 286351, 286351003-100, 286351003-101, 286351-2, 286351002-1, 286351002-2, 286351003-102, 286351003-103, 286351-1, 286351001-1, 286351001-2, Wheel, Messier-Bugatti, are added.</p> |
| 02 | 12.03.2009 | <p>P/Ns: RPS1-B & 2013-1A, Battery Power Supply & Battery Holder Assembly, Radiant Power Corp., are added.</p> |
| 03 | 29.04.2009 | <p>P/Ns: 3-1423-1 & 3-1423-2 (Boeing P/N S160N010-30 & Boeing P/N S160N010-31), Nose Landing Gear Wheel Assembly, Goodrich, are added.</p> <p>P/Ns: 3-1422, 3-1427, 3-1428, Main Wheel Assembly, Goodrich, are added.</p> <p>P/Ns: 2-1457, 2-1457-1, 2-1457-2, Main Landing Gear Brake Assembly, Goodrich, are added.</p> <p>P/Ns: 680-0021-300, 680-0021-310, 680-0021-320, Windshield Temperature Regulator, Electronique Aerospatiale, are added.</p> <p>P/Ns: BPS7-2 (Boeing SCD S283T014-2), BPS7-3 (Boeing SCD S283T014-3), Battery Power Supply, Radiant Power Corp., are added.</p> <p>P/Ns: 60-0304-31, 60-0304-33, 60-0304-51, Rechargeable Power Failure Battery Power Supply, Honeywell, are added.</p> <p>P/Ns: C20211170, C20211171, C20211172, Wheel, Messier-Bugatti, are added.</p> <p>P/Ns: C20211100, C20211100-1, C20211100-2, C20211100-3, C20211101, C20211101-1, C20211101-2, C20211101-3 Wheel, Messier-Bugatti, are added.</p> <p>P/Ns: C20211000, C20211000-1, C20211000-2, C20211000-3, C20211000-4, C20211000-5, C20211000-6, C20211001, C20211001-1, C20211001-2, C20211001-3, C20211001-4, C20211001-5, Wheel, Messier-Bugatti are added.</p> <p>P/Ns: C20211150, C20211150-1, C20211150-2, C20211150-3, C20211160, C20211151, C20211151-1, C20211151-2, C20211151-3, C20211161, Wheel, Messier-Bugatti are added.</p> <p>P/Ns: 289021-1001, 289021-1002, 289021-1201, 289021-1202, 289021022, 289021022-1, 289021022-2, 28921322, 28921322-1, Wheel, Messier-Bugatti are added.</p> <p>P/Ns: C20210500-1, C20210500-2, C20210500-3, C20210500-4, C20210500-5, C20210500-6, C20210500-7, C20210500-8, C20210500-9, Carbon Brake, Messier-Bugatti, are added.</p> <p>P/Ns: C20210601, C20210602, C20210603, C20210604, C20210605, C20210606, C20210607, C20210610, Carbon Brake, Messier Bugatti, are added.</p> |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|--|
| 04 | 10.07.2009 | <p>P/Ns:2-1474-5 & 2-1474-7 (Boeing P/Ns: 10-61819-31 & 10-61819-35), Main Landing Gear Brake Assembly, Goodrich, are added.</p> <p>P/Ns: PU90-401R1, PU90-401R2, PU90-401R3, PU90-401R4, PU90-401S, PU90-421R1, PU90-421R2, PU90-421R3,</p> <p>PU90-421R4, PU90-421S, PU90-431R1, PU90-431R2, PU90-431R3, PU90-431R4, PU90-431S, PU90-441R1, PU90-441R2, PU90-441R3, PU90-441R4, PU90-441S, PU90-451R1, PU90-451R2, PU90-451R3, PU90-451R4, PU90-451S, PU90-461R1, PU90-461R2, PU90-461R3, PU90-461R4, PU90-461S, PU90-499R1, PU90-499R2, PU90-499R3, PU90-499R4, PU90-499S, Smoke Detector, JAMCO Corporation, are added.</p> <p>P/Ns: P0723E105P & VARIANTS, P0723E109P & VARIANTS, P0723E129P & VARIANTS, Adult/Child Life Preserver (Model KSE-35L8), Eastern Aero Marine, are added.</p> <p>P/Ns: 69-54784-1, 69-69882-1, 69-69882-2, 69-69882-3, 69-69882-4, 69-69882-5, 69-69882-6, Swivel Assembly, Boeing are added.</p> |
| 05 | 14.07.2009 | P/N's :P0640-101 and Variants, P0640-103 and Variants, P0640-105 and Variants, P0640-109 and Variants, P0640-111 and Variants, P0640-113 and Variants, P0640-115 and Variants, P0640-117 and Variants, Infant Life Preserver Model IN-V20L8, Eastern Aero Marine, are added. |
| 06 | 21.08.2009 | P/N's 310A020-1, 310A1020-19, 310A1020-3, CFM56 Engine Mount Components added |
| 07 | 09.09.2009 | Rating: C14, P/N's 5930583 and variants BOEING Main gear inboard door installation added. Rating: C7, P/N's 5938050-1/501/503/505/507 Thrust Reverse Assembly added. |
| 08 | 13.10.2009 | Rating: C7, P/N's 405FW504-B Honeywell Solid State Proximity Switch PC Assembly added. Rating: C8, P/N's 8-060-02 (BOEING 10-61226-211), 8-060-07 (BOEING 10-61226-213) and 8-060-10 Crane Eldec orporation Solid State Proximity Switch PC Assembly added. Rating: C18, P/N's 231-2, Primex Aerospace Company Windshield Temperature Controller added. |
| 09 | 21.10.2009 | Rating: C5, P/N AD-4579 Aero Design Nickel Cadmium Battery added. Rating: C5, P/N AD-43B034LB03 Aero Desing Aircraft Battery added. |
| 10 | 26.10.2009 | Rating: C9, P/N 2S2542 CRISSAIR Valve-swing check added. |
| 11 | 30.10.2009 | Rating: C6, P/N P01074-1XX (Model XF-35) EASTERN AERO MARINE Adult/Child Life Preserver and container Assembly added. Rating: C7, P/N 5930649-1, 5930649-2, 5930649-501, 5930649-502, 5930649-503, 5930649-504, 5930649-505, 5930649-506, 5930649-507, 5930649-508 BOEING Upper Cowl Door Assembly added. Rating: C14, P/N 2606801-1, P/N 2606801-2, P/N 2606801-3, P/N 2606801-4 Honeywell Main Wheel Assembly and axle sleeves added. Rating: C18, P/N 102-00074 Norwich Aero Ice Protection Low Temperature Sensor added. Rating: C18, P/N 102-00075 Norwich Aero Ice Protection High Temperature Sensor added. |
| 12 | 03.11.2009 | Rating: C8, P/N 5922500-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -517, -518, -519, -520, -521, -522, -523, -524, -525, -526, -527, -528, 5922532-1, -2, -501, -502, -503, -504, 5922532-505, -506, -507, -508, -509, -510, -513, -514, 5922533-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -515, -516, 5922534-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -515, -516, -517, -518, -519, -520, -521, -522, 5922535-1, -2, -501, -502, -505, -506, -507, -508, 5937415-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -515, -516, -517, -518, 5937563-1, -2, -501, -502, -503, -504, -505, -506, -507, -508 BOEING Wing Slat Assembly added |
| 13 | 09.11.2009 | Rating: C1, P/N AYL9714, AYL9714-1 (optional to 102-00074 as listed on IPC) Smiths Aerospace Temperature Sensor added. |
| 14 | 17.11.2009 | Rating: C14, P/N 273A1101-1, BOEING nose landing gear retract actuator assembly added. Rating: C8, P/N 65-44851-3/-4/-5/-6/-7/-10/-12/-13/14 BOEING ground spoiler locking actuator added. Rating: C14, P/N 2606802-3/-4/-5 Allied Signal main brake assembly added. Rating: C5, P/N 32248-001 (type BTSP-4445L) nickel cadmium battery added. |
| 15 | 02.12.2009 | Rating: C1, P/N 683478-1-1, P/N 683478-1, P/N 683478-2, P/N 683478-3 Honeywell (Allied Signal) Thermal Switch added. |
| 16 | 14.12.2009 | Rating: C1, P/N 572757-1 Allied signal Aerospace – Airesearch Los Angeles Division Turbine Inlet Thermal Switch added. Rating: C18, P/N 1241X-XXX-XXX, 67XXX-XXX-XXX, 68021-000-XXX Fenwal Safety Systems Midget thermostwitch unit line added. |
| 17 | 18.12.2009 | Rating: C6, P/N D29982-103, D29982-107, D29982-109, D29982-111, D29982-113, D29982-119, D29982-121, D29982-123, D29982-125, D29982-127, Air Cruisers forward passenger/service door evacuation slide assy added. |
| 18 | 30.12.2009 | Rating: C5, P/N 40253 (P/N 019654-000) SAFT Nickel – Cadmium Aircraft Battery added. Rating: C6, P/N Model FV-35E & F (-100, -200, -400 & -500 Series) Hoover Industries Flotation Vest added. Rating: C6, P/N S-61XXX-() Series Switlik Parachute Company Life Preserver Model AV-35 added. Rating: C6, P/N S-10002-() Series Switlik Parachute company Life Preserver Model ILV-20 added. Rating: C14, P/N 2608891-1, 2608891-1A, 2608891-1B, 2608891-1C Honeywell MD80 Series main whell assembly added. |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|---|
| | | Rating: C14, P/N 9550267, 9550267-2, 9550267-3, 9550267-5, 9550267-6, 9550267-6A, 9550267-7, 9550267-7A ABSC Nose wheel added. |
| 19 | 14.01.2010 | Rating: C5, P/N G-25, G-35, G-35M, G-88, G-240, G-241, G-242, G-243, G-244, G-245, G-246 GILL Teledyne battery products added. Rating: C5, 276CH1 SAFT Aircraft battery added. Rating: C5, P/N 40253 (P/N 019654-000), 40208, 40208-1, 40208-2, 40208-4, 40208-5, 40208-6, 40208-7 SAFT Nickel-cadmium aircraft battery added. Rating: C6, P/N P0723-101, P0723-103, P0723-105, P0723-107, P0723-109, P0723-111, P0723-113, P0723-115, P0723-117, P0723-119, P0723-121, P0723-123, P0723-125, P0723-127, P0723-201, P0723-203, P0723-205, P0723-301, P0723-303, P0723-401, P0723-403, P0723-405, P0723-501, P0723-503, P0723-601 EAM Adult/child life preserver added. |
| 20 | 15.01.2010 | Rating: C5, P/N 10-0119-1, 10-0119-3 Grimes Emergency Exit Light added. Rating: C5, P/N 10-0519-1, 10-0519-3, 10-0519-5, 10-0519-7, 10-0519-9, 10-0519-11 Honeywell Emergency Light Assembly added. Rating: C5, P/N 915F213-2 Hamilton Sundstrand bus protection panel added. |
| 21 | 15.01.2010 | Rating: C6, P/N D29985-103, D29985-107, D29985-109, D29985-111, Air Cruisers Aft service door evacuation slide added. Rating: C6, P/N D29984-103, D29984-109, D29984-113, D29984-119, D29984-211, D29984-213 Air cruisers tail cone emergency exit evacuation slide added. Rating: C6, P/N D31591-448, D31591-449, D31591-450, D31591-451, D31591-452, D31591-453, D31591-454, D31591-458, D31591-459, D31591-460, D31591-461, D31591-462, D31591-463, D31591-464, D31591-474, 91-475, D31591-476, D31591-477, D31591-478, D31591-479, D31591-480, D31591-487, D31591-488, D31591-489 Air Cruisers forward door lightweight evacuation slide added. |
| 22 | 25.01.2010 | Rating: C6, P/N D30664-101, D30664-103, D30664-105, D30664-107, D30664-109, D30664-305, D30664-307, D30664-309, D30664-311, D30665-101, D30665-103, D30665-105, D30665-107, D30665-109, D30665-305, D30665-307, D30665-309, D30665-311 Air Cruisers / Aerazur Evacuation Slide / Raft added. |
| 23 | 26.01.2010 | Rating: C6, P/N D31865-101 (LH), D31865-103 (LH), D31865-105 (LH), D31865-107 (LH), D31865-109 (LH), D31865-111 (LH), D31865-209 (LH), D31865-102 (RH), D31865-104 (RH), D31865-106 (RH), D31865-108 (RH), D31865-110 (RH), D31865-112 (RH), D31865-210 (RH) Air Cruisers/Aerazur Dual Lane off-wing ramp/slide added. Rating: C6, P/N 61621-469 (BOEING 10-61323-469) Air Cruisers Aft Door Evacuation Slide added. Rating: C14, P/N 3-1530, 3-1530 OPT2, 3-1530 OPT3, 3-1530 OPT4, 3-1530-1 OPT2, 3-1530-1 OPT3, 3-1530-1 OPT4 Goodrich Main Landing Gear Wheel Assembly. |
| 24 | 22.02.2010 | Rating: C20, P/N A5726000000051, A5726000000151, A5726006000051, A5726006000151, A5726006000251, A5726006000451, A5726006000651, A5726006000751, A5726006000851, A5726006000951, A5726000000052, A5726000000152, A5726006000052, A5726006000152, A5726006000154, A5726006000351, A5726006000551, A5726006000652, A5726006000752, A5726006000852, A5726006000952, A5726006000151 AIRBUS S.A.S. Wing Tip added. |
| 25 | 04.03.2010 | Rating: C5, P/N 4-254-02, 4-254-02 MOD1, 4-254-03, 4-254-04, BOEING P/N: S282T002-2, S282T002-4, S282T002-5, S282T002-6 Crane Eldec Corporation Battery Charger added. CCS-001 Authorized personnel stamp number added as " He is authorized to perform maintenance in accordance with related CMM which under myTECHNIC capability and issue a CRS document for aircraft batteries only". |
| 26 | 11.03.2010 | Rating: C5, P/N AD-2758, SAFT Aircraft Battery added. |
| 27 | 15.03.2010 | Rating: C14, P/N 5007897-1, 5007897-2, 5007897-3 ABSC Main Wheel Assembly added. |
| 28 | 31.03.2010 | Rating: C5, P/N 1756-1, -3, SAFT Aircraft Battery added. Rating: C5, P/N 4078-3, 4078-24, 40178-24, 40178-26 SAFT Aircraft Battery added. Rating: C5, P/N Type Part Number M3-28-1 33206-001 M 3X-33-1 33181-001 M3-44-1 32663-001 TM3-44-4 32794-001 M3-44-7 32824-001 M3-44-8 32845-001 M3-44-9 32848-001 M3-44-11 32857-001 M3-44-15 32890-001 M3-44-21 33008-001 M3-44-22 33204-001 M3-460L-1 31006-004 M3-460L-1A 31006-006 M3-54-1 32536-001 M3-54-2 33033-001 M3X-54-1 33183-001 20-60M3X100 33006-001 M81757/15-1 32744-001 M81757/15-2 32775-001 M81757/15-3 32764-001 M81757/16-1 32477-001 M81757/18-1 33152-001 7-75M3120 32364-001 Marathon Norco Aerospace Nickel Cadmium Aircraft Battery added. |
| 29 | 04.04.2010 | Rating: C5, P/N 32794-001, Marathon Norco Aerospace, Micro Maintenance Nickel Cadmium Aircraft Battery added. |
| 30 | 27.04.2010 | Rating: C6, P/N FV-35 Series, Hoover Industries, Flotation vest added. Rating: C6, P/N 63600 series, Air Cruisers, AC2000 Life Preserver added. Rating: C6, P/N D31354-425, D31354-426, D31354-429, D31354-433, D31354-434, D31354-435, D31354- |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|--|
| | | 437, D31354-438, D31354-439, D31354-442, D31354-443, D31354-447, Air Cruisers Aircraft Evacuation Slide added. |
| 31 | 04.05.2010 | Rating: C5, P/N30-0909-1, 30-0909-101, 30-0909-103, 30-0909-107, 30-0909-201, 30-0909-203, 30-0909-207, Grimes Aerospace Aircraft Tail Position Flashtube light added. CCS-001 certifying staff number deleted. |
| 32 | 26.05.2010 | The following component maintenances are suspended due to lack of certifying staff; Rating: C4, 65-62238-1, 65-62238-2, Cargo Door Latch Actuator Assembly, Boeing Rating: C7, 968214-1, 968214-2, 968214-3, 968214-4, 968214-5, 968214-6, 968214-7, 968214-8, 968214-9, 968214-10, 968214-11, 968214-12, 968214-13, 968214-14, 968214-15, 968214-17, Pressure Relief Valve Assembly, Allied-Signal Aerospace Company Rating: C7, 21SN41-42, 21SN41-52, 21SN41-84, Pressure Switch, Eaton Rating: C8, 65-44851-3/-4/-5/-6/-7/-10/-12/-13/-14, Ground Spoiler locking Actuator, BOEING Rating: C12, 90G118-2, Pressure Switch, Custom Component Switches, Inc Rating: C12, 69-54784-1, 69-69882-1, 69-69882-2, 69-69882-3, 69-69882-4, 69-69882-5, 69-69882-6, Swivel Assembly, Boeing Rating: C14, 2606802-3, 2606802-4, 2606802-5, Main Brake Assembly, Allied signal Rating: C14, 3-1531, 3-1531-1, 3-1531-2, 3-1531-3, Nose Landing Gear Wheel Assembly, Goodrich Rating: C14, 2607825-1, 2607825-2, Nose Wheel Assembly, Honeywell Rating: C14, 2609801-1, Main Wheel Assembly, Honeywell Rating: C14, 2606671-1, 2606671-2, 2606671-3, Main Wheel Assembly, Honeywell Rating: C14, 2612311-1, Main Wheel Assembly, Honeywell Rating: C14, 2606672-1, 2606672-2, 2606672-3, 2606672-4, Main Brake Assembly, Honeywell Rating: C14, 2612312-1, Main Brake Assembly Honeywell Rating: C14, 3937860-5001, 3937860-5002, 3937860-5501, 3937860-5502, Main Landing Gear Retract Cylinder Gland Assembly Douglas Aircraft Company Rating: C14, 286351006, 286351006-1, 286351007, 286351007-1 Wheel Messier-Bugatti Rating: C14, 286351005, 286351005-1 Wheel Messier-Bugatti Rating: C14, 286351004, 286351004-1, 286351004-2 Wheel Messier-Bugatti Rating: C14, C21928, C21928-1, 286351003, 286351003-1, 286351003-2, 286351003-3, 286351, 286351003-100, 286351003-101, 286351-2, 286351002-1, 286351002-2, 286351003-102, 286351003-103, 286351-1, 286351001-1, 286351001-2 Wheel Messier-Bugatti Rating: C14, 3-1423-1, (Boeing P/N S160N010-30), 3-1423-2 (Boeing P/N S160N010-31) Nose Landing Gear Wheel Assembly Goodrich Rating: C14, 3-1422, 3-1427, 3-1428, Main Wheel Assembly Goodrich Rating: C14, 2-1457, 2-1457-1, 2-1457-2, Main Landing Gear Brake Assembly, Goodrich Rating: C14, C20211170, C20211171, C20211172, Wheel Messier-Bugatti Rating: C14, C20211100, C20211100-1 C20211100-2 C20211100-3 C20211101, C20211101-1 C20211101-2 C20211101-3, Wheel Messier-Bugatti Rating: C14, C20211150, C20211150-1 C20211150-2 C20211150-3, C20211160, C20211151, C20211151-1 C20211151-2, C20211151-3, C20211161, Wheel Messier-Bugatti Rating: C14, 289021-1001, 289021-1002, 289021-1201, 289021-1202 289021022, 289021022-1 289021022-2 28921322, 28921322-1, Wheel Messier-Bugatti Rating: C14, C20210500-1, C20210500-2, C20210500-3, C20210500-4, C20210500-5, C20210500-6, C20210500-7, C20210500-8, C20210500-9 Carbon Brake Messier-Bugatti Rating: C14, C20210601, C20210602, C20210603, C20210604, C20210605, C20210606, C20210607, C20210610, Carbon Brake Messier-Bugatti Rating: C14, 2-1474-5, 2-1474-7, (Boeing P/Ns: 10-61819-31 & 10-61819-35) Main Landing Gear Brake Assembly Goodrich Rating: C14, 2606801-1, 2606801-2, 2606801-3, 2606801-4, Main Wheel Assembly and Axle Sleeves Honeywell Rating: C14, 273A1101-1, Nose Landing Gear Retract Actuator Assembly, BOEING Rating: C14, 2608891-1, 2608891-1A, 2608891-1B, 2608891-1C, MD80 Series Main Wheel Assembly Honeywell Rating: C18, 2314M-10, 2314M-17, 2314M-37, 2314M-38, 2314M-69, 2314M-72, Windshield Wiper Belleville Washer Arm Assemblies Rosemount Aerospace Inc. Rating: C20, LM-321-SA15, Aircraft Engine Mounting System Lord Aerospace Products Rating: C20, LM-321-118, LM-321-118H, Aircraft Engine Mounting System Lord Corporation Rating: C20, LM-321-57, LM-321-58, Aircraft Engine Mounting System Lord Corporation |
| 33 | 28.05.2010 | Rating: C5, Model No: 4025CH1, P/N: 023964-000, SAFT, Nickel Cadmium Battery added. |
| 34 | 10.06.2010 | Some of the suspended parts have been activated again. |
| 35 | 22.06.2010 | Rating: C6, P/N: A29785-103-1-21, A29785-104-1-21, A29785-105-1-21, A29785-106-1-21, A29785-107-1-21, A29785-108-1-21, A29785-109-1-21, A29785-110-1-21, A29785-105-1-22, A29785-106-1-22, A29785-107-1-22, A29785-108-1-22, A29785-109-1-22, A29785-110-1-22, A29785-105-1-33, A29785-106-1-33, A29785-107-1-33, A29785-108-1-33, A29785-109-1-33, A29785-110-1-33, A29786-105-1-21, A29786-106-1-21, A29786-107-1-21, A29786-108-1-21, A29786-109-1-21, A29786-110-1-21, A29786-111-1-21, A29786-112-1-21, A29786-107-1-22, A29786-108-1-22, A29786-109-1-22, A29786-110-1-22, A29786-111-1-22, A29786-112-1-22, A29786-107-1-33, A29786-108-1-33, A29786-109-1-33, A29786-110-1-33, A29786-111-1-33, A29786-112-1-33, A29784-103-1-21, A29784-104-1-21, A29784-105-1-21, A29784-106-1-21, A29784-107-1-21, A29784-108-1-21, A29784-105-1-22, A29784-106-1-22, A29784-107-1-22, A29784-108-1-22, A29784-105-1-33, A29784-106-1-33, A29784-107-1-33, A29784-108-1-33, Systems Air Cruisers A300 Evacuation Slide added as "suspended". Rating: C6, A30466-101-1-21, A30466-102-1-21, A30466-103-1-21, A30466-104-1-21, A30466-101-1-22, A30466-102-1-22, A30466-103-1-22, A30466-104-1-22, A30466-101-1-31, A30466-102-1-31, A30466-103-1-31, A30466-104-1-31, A30466-101-1-33, A30466-102-1-33, A30466-103-1-33, A30466-104-1-33, A30476-101- |

| Revizyon No Revision Number | Revizyon Tarihi Revision Date | Revizyonun Tanımı Description of the Revision |
|--------------------------------|----------------------------------|--|
| | | <p>1-21, A30476-102-1-21, A30476-103-1-21, A30476-104-1-21, A30476-101-1-22, A30476-102-1-22, A30476-103-1-22, A30476-104-1-22, A30476-101-1-31, A30476-102-1-31, A30476-103-1-31, A30476-104-1-31, A30476-101-1-33, A30476-102-1-33, A30476-103-1-33, A30476-104-1-33, D30457-103, D30457-104, D30457-105, D30457-106, D30457-107, D30457-108, D30457-109, D30457-110, D30457-111, D30457-112, D30457-113, D30457-114, D30457-115, D30457-116, D30457-117, D30457-118, D30477-103, D30477-104, D30477-105, D30477-106, D30477-107, D30477-108, D30477-109, D30477-110, D30477-111, D30477-112, D30477-113, D30477-114, D30477-115, D30477-116, D30477-117, D30477-118, Air Cruisers, A300 Slide/Raft Evacuation systems added as "suspend".</p> <p>Rating: C6, 8101-01-4000, 8101-01-4000-1, 8101-01-4000B, 8101-01-4000B1, 8101-01-4000C, 8101-01-4000C1, SELL, Oven Control Module added as "suspend".</p> <p>Rating: C18, KOITO PART NO: 83000-05601, 83000-05601, 83000-05602, BOEING PART NO: 10-61833-1, 10-61833-2, 10-61833-3, KOITO MFG CO LTD, WINDOW HEAT CONTROL UNIT added as "suspend".</p> <p>Rating: C18, KOITO PART NO: 83000-05603, 83000-05604, BOEING PART NO: 10-61833-4, 10-61833-6, KOITO MFG CO LTD, WINDOW HEAT CONTROL UNIT added as "suspend".</p> <p>Rating: C6, CRANE ELDEC P/N: 8-930-03, 8-930-03 MOD A, BOEING P/N: S282T003-3, CRANE ELDEC Battery Charger added as "suspend".</p> <p>Rating: C6, D31041-140, -147 (BOEING P/N: S416N202-40, -47), D31041-139, -146 (BOEING P/N: S416N202-39, -46), Air Cruisers 757 Aircraft slide system added as "suspend".</p> <p>Rating: C6, D30546-101, D30546-109, D30546-205, D30545-101, D30546-203, D30546-103, D30546-201, D30546-207, D30545-103, D30545-207, D30546-105, D30546-203, D30546-209, D30545-107, D30545-201, D30546-107, Air Cruisers FWD/AFT/MID Door Dual Lane Slide/Raft Evacuation Slide added as "suspend".</p> <p>Rating: C6, D30658-114, -117, -120, -123, -314, -317, -320, -323, -333, (BOEING P/Ns: S416N202-3014, -3017, -3020, -3023, -3314, -3317, -3320, -3323, -3333), D30655-114, -117, -120, -123, -133 (BOEING P/Ns: S416N202-1014, -1017, -1020, -1023, -1033), Air Cruisers 757 A/C single lane slide/raft system door 2 LH/RH added as "suspend".</p> <p>Rating: C6, DOOR 4 L.H. ACC 61570-127, -327 (BOEING P/N: S416N202-3027, -3327) 61571-127 (BOEING P/N: S416N202-1027), DOOR 4 R.H. ACC 61570-128, -328 (BOEING P/N: S416N202-3028, -3328) 61571-128 (BOEING P/N: S416N202-1028), Air Cruisers, High Gross Weight Aircraft Evacuation slide/Raft System added as "suspend".</p> <p>Rating: C6, D30657-113, -116, -119, -122, -313, -316, -319, -322, -331 (BOEING P/N: S416N202-3013, 3016, 3019, 3022, 3313, 3316, 3319, 3322, 3331), D30654-113, -116, -119, -122, -131 (BOEING P/N: S416N202-1013, 1016, 1019, 1022, 1031), Air Cruisers, 757 Aircraft single Lane Slide/Raft system and assembly added as "suspend".</p> <p>Rating: C5, 915F212-4, 915F212-5, 915F212-6, 915F212-7, 915F212-8, Hamilton Sunstrand, Generator Control Unit, added as "suspend".</p> <p>Rating: C5, 948F458-1, 948F458-2, 948F458-3, 948F458-4, 948F458-5, Hamilton Sunstrand, Generator Control Unit, added as "suspend".</p> <p>Rating: C6, D213443 Series and D213444 (Serial Numbers L750000 and subsequent and C700000 through C749999 only), Air Cruisers, AC-2F and AC-2CF Life Preserver added as "suspend".</p> |
| 36 | 02.07.2010 | Rating: C5, 1656-6, SAFT, Aircraft Batteries added. |
| 37 | 06.07.2010 | Rating: C6, Crane Eldec P/N: 8-930-03, Boeing P/N: S282T003-3, Crane Eldec, Battery Charger activated. Rating: C14, 3-1484 (BOEING P/N: 10-62174-1), Goodrich, Main Wheel Assembly added as "suspend". |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|--|---|--|---|--|---------------------------------|
| C1 | 102-00074 | Air Conditioning High Temperature Sensor | Norwich Aero Products | Inspection/Test Modification | 21-00-11 | CCS-857 | 23.06.2009 |
| C1 | 3000-46-2 3000-46-5 3000-46-7 3000-46-12 3000-46-13 3000-46-14 3000-46-15 3000-46-16 3000-46-18 3000-46-19 3000-46-20 3000-46-21 3000-46-22 3000-46-23 3000-46-24 3000-46-27 3000-46-28 3000-46-29 3000-46-32 3000-46-41 3000-46-42 3000-46-43 3000-87-2 3000-462-1 3000-608-1 3100-3-218 3100-81-1 3100-101-1 3100-101-3 3100-101-4 3100-101-6 3100-119-2 3100-119-3 3100-160-16 3100-190-12 3100-241-1 3100-250-1 3100-250-2 3100-250-3 3100-250-4 3100-250-5 3100-250-6 3100-262-1 3100-262-2 3100-262-3 3100-262-4 3100-292-1 3800-32-3 | Thermal Switch Assembly | Honeywell – Elmwood Sensors Inc. | Inspection/Test Modification | 21-43-01 | CCS-857 | 28.10.2008 |
| C1 | 641121-1 | Overheat Zone Duct Switch | Honeywell | Inspection/Test Modification | 21-51-46 | CCS-857 | 28.10.08 |
| C1 | 641172-1 | Pack Discharge Overhead Switch | Garrett – Airesearch | Inspection/Test Modification | 21-52-08 | CCS-857 | 28.10.08 |
| C1 | 641109-1 641109-2 641109-3 641109-4 641109-5 | Thermal Switch | Honeywell (Allied-Signal) | Inspection/Test Repair Modification Reassembly | 21-52-06 | CCS-857 | 23.02.2009 |
| C1 | 572756-1 | Thermal Switch | Allied Signal Aerospace – Airesearch Los Angeles Division | Inspection/Test Repair Modification Reassembly | 21-52-24 | CCS-857 | 24.02.2009 |
| C1 | AYLF9714 AYLF9714-1 (optional to 102-00074) | Temperature Sensor | Smiths Aerospace | Inspection/Test Modification | F-14089 | CCS-857 | 09.11.2009 |
| C1 | 683478-1-1, 683478-1, 683478-2, 683478-3 | Thermal Switch | Honeywell (Allied Signal) | Inspection / Test Reassembly Modification | 21-62-20 | CCS-857 | 02.12.2009 |

myTECHNIC KOMPONENT BAKIMI KABİLİYETİ LİSTESİ

myTECHNIC COMPONENT MAINTENANCE CAPABILITY LIST

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|------------------------------------|--|---|---|--|---------------------------------|
| C1 | 572757-1 | Turbine inlet thermal switch | Allied Signal Aerospace – Airsearch Los Angeles Division | Inspection/Test Repair Reassembly Modification | 21-52-20 | CCS-857 | 14.12.2009 |
| C3 | 69-68010-1 69-68010-3 69-68010-6 69-68010-8 69-68010-10 69-68010-11 | Telephone Printed Circuit Assy | Boeing | Inspection / Test Repair Modification | 23-01-05 | CCS-857 | 28.10.2008 |
| C3 | 1201 12101 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 34-41-01 | CCS-857 | 19.12.2008 |
| C4 | 65-62238-1 65-62238-2 | Cargo Door Latch Actuator Assembly | Boeing | Inspection / Test Modification | 52-30-61 | CCS-998 | 27.10.2008 |
| C5 | 2520 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-11 | CCS-857 | 18.07.2008 |
| C5 | 2758 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-38-51 | CCS-857 | 18.07.2008 |
| C5 | 539CH-1 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-07 | CCS-857 | 18.07.2008 |
| C5 | 40176-4 40176-7 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-32-03 | CCS-857 | 18.07.2008 |
| C5 | 28695-001 | Nickel-Cadmium Aircraft Battery | Marathon Norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-00 | CCS-857 | 18.07.2008 |
| C5 | 30475-002 | Nickel-Cadmium Battery | Marathon Norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-01 | CCS-857 | 18.07.2008 |
| C5 | 30874-001 | Aircraft Battery | Marathon Norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-02 | CCS-857 | 18.07.2008 |
| C5 | 605A 605B | Aircraft Nickel Cadmium Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-19 | CCS-857 | 18.07.2008 |
| C5 | 23578 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-33-02 | CCS-857 | 19.12.2008 |
| C5 | 4608-1 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-33-01 | CCS-857 | 19.12.2008 |

myTECHNIC KOMPONENT BAKIMI KABİLİYETİ LİSTESİ

myTECHNIC COMPONENT MAINTENANCE CAPABILITY LIST

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|------------------------------------|--------------------------------|---|---|--|---------------------------------|
| C5 | 4579 (BA06 ELDEC Part Number) (S282T002-1 BOEING Part Number) (Saft Part Number 018550-000) | Aircraft Nickel Cadmium Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-05 | CCS-857 | 19.12.2008 |
| C5 | 43B034LB03 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-30-02 | CCS-857 | 19.12.2008 |
| C5 | 3121-01 | Emergency Light Supply Unit | Diehl | Inspection/Test | 33-51-04 | CCS-857 | 19.12.2008 |
| C5 | 60-1177-5 60-1177-7 60-1177-9 | Battery Power Supply | Grimes Division Company | Inspection/Test | 33-50-12 | CCS-857 | 19.12.2008 |
| C5 | 20108 20108-1 | Aircraft Battery | Saft | Inspection/Test Repair Reassembly Overhaul Modification | 24-30-00 | CCS-857 | 23.02.2009 |
| C5 | 23175 23176 2376 2376-1 2376-4 | Cadmium Nickel Storage Battery | Saft | Inspection/Test Repair Reassembly Overhaul Modification | 24-35-06 | CCS-857 | 23.02.2009 |
| C5 | 2778-1 | Aircraft Battery | Saft | Inspection/Test Repair Reassembly Overhaul Modification | 24-30-00 | CCS-857 | 23.02.2009 |
| C5 | 1152552-1 | 40 AHR Battery | Honeywell | Inspection/Test Repair Reassembly Overhaul Modification | 24-34-04 | CCS-857 | 24.02.2009 |
| C5 | 23491 23491-3 | Aircraft Battery | Saft | Inspection/Test Repair Reassembly Overhaul Modification | 24-30-00 | CCS-857 | 23.02.2009 |
| C5 | Marathon Micro Maintenance (M ³) (Applicable to M ³ -28-1, M ³ X-33-1, M ³ -44-1, TM ³ -44-4, M ³ -44-7, M ³ -44-8, M ³ -44-9, M ³ -44-11, M ³ -44-15, M ³ -44-21, M ³ -44-22, M ³ -460L-1, M ³ -460L-1A, M ³ -54-1, M ³ -54-2, M ³ X-54-1, 20-60M ³ X100, M81757/15-1, M81757/15-2, M81757/15-3, M81757/16-1, M81757/18-1, 7-75M ³ 120) | Nickel Cadmium Aircraft Battery | Marathon Norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-08 | CCS-857 | 24.02.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|---|--------------------------------|--|---|--|---------------------------------|
| C5 | 915F213-3 915F213-4 | Bus Protection Panel | Hamilton Sunstrand | Inspection/Test | 24-20-61 | CCS-857 | 22.02.2009 |
| C5 | 60-0304-31, 60-0304-33, 60-0304-51 | Rechargeable Power Failure Battery Power Supply | Honeywell | Inspection/Test | 33-50-02 | CCS-857 | 02.04.2009 |
| C5 | AD-43B034LB03 | Aircraft Battery | Aero Design | Inspection/Test Repair Reassembly Overhaul Modification | 24-30-02 | CCS-857 | 21.10.2009 |
| C5 | 32248-001 (type BTSP- 4445L) | nickel cadmium battery | Allied Signal | Inspection/Test Repair Reassembly Overhaul Modification | 24-34-04 | CCS-857 | 16.11.2009 |
| C5 | AD-4579 | Nickel Cadmium Battery | Aero Design | Inspection/Test Repair Reassembly Overhaul Modification | 24-31-05 | CCS-857 | 21.10.2009 |
| C5 | 40253 (019654-000) | Nickel Cadmium Battery | SAFT | Inspection/Test Reassembly Overhaul Modification Repair (for repair, bearing cup and tie-bolt hole radius is excluded) | 24-30-99 | CCS-857 | 28.12.2009 |
| C5 | G-25, G-35, G-35M, G- 88, G-240, G-241, G- 242, G-243, G-244, G- 245, G-246 | Teledyne battery products | GILL | Inspection/Test Reassembly Overhaul Modification Repair | 12-08-06 8-17-07 | CCS-857 | 14.01.2010 |
| C5 | 276CH1 | Aircraft battery | SAFT | Inspection/Test Reassembly Overhaul Modification Repair | 24-30-24 | CCS-857 | 14.01.2010 |
| C5 | 40253 (P/N 019654-000), 40208, 40208-1, 40208- 2, 40208-4, 40208-5, 40208-6, 40208-7 | Nickel-cadmium aircraft battery | SAFT | Inspection/Test Reassembly Overhaul Modification Repair | 24-30-99 | CCS-857 | 14.01.2010 |
| C5 | 10-0119-1, 10-0119-3 | Emergency Exit Light | Grimes | Inspection/Test | 33-50-05 | CCS-857 | 15.01.2010 |
| C5 | 10-0519-1, 10-0519-3, 10-0519-5, 10-0519-7, 10-0519-9, 10-0519-11 | Emergency Light Assembly | Honeywell | Inspection/Test | 33-51-11 | CCS-857 | 15.01.2010 |
| C5 | 915F213-2 | Bus protection panel | Hamilton Sundstrand | Inspection/Test | 24-20-63 | CCS-857 | 15.01.2010 |
| C5 | 4-254-02, 4-254-02 MOD1, 4-254-03, 4-254- 04, BOEING P/N: S282T002-2, S282T002-4, S282T002-5, S282T002-6 | Battery Charger | Crane Eldec Corporation | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-04 | CCS-857 | 04.03.2010 |
| C5 | AD-2758 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-38-51 | CCS-857 | 11.03.2010 |
| C5 | 1756-1, 1756-3 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-32-06 | CCS-857 | 31.03.2010 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorized Staff Stamp Number | Onay Tarihi Approval Date | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--------------------------|---|---|--------------------------------|--|---|--|---------------------------------|----------------------|-----------|-----------------------|-----------|----------------------|-----------|----------------------|-----------|----------------------|-----------|-----------------------|-----------|-----------------------|-----------|-----------------------|-----------|-----------------------|-----------|------------------------|-----------|-------------------------|-----------|----------------------|-----------|----------------------|-----------|-----------------------|-----------|--------------------------|-----------|-------------|-----------|-------------|-----------|-------------|-----------|-------------|-----------|-------------|-----------|------------------------|-----------|------------------------------------|-----------------------------|---|----------|---------|------------|
| C5 | 4078-3, 4078-24, 40178-24, 40178-26 | Aircraft Battery | Saft | Inspection/Test Repair Overhaul Reassembly Modification | 24-32-05 | CCS-857 | 31.03.2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | <table border="1"> <thead> <tr> <th>Type</th> <th>Part Number</th> </tr> </thead> <tbody> <tr><td>M³-28-1</td><td>33206-001</td></tr> <tr><td>M³X-33-1</td><td>33181-001</td></tr> <tr><td>M³-44-1</td><td>32663-001</td></tr> <tr><td>TM³-44-4</td><td>32794-001</td></tr> <tr><td>M³-44-7</td><td>32824-001</td></tr> <tr><td>M³-44-8</td><td>32845-001</td></tr> <tr><td>M³-44-9</td><td>32848-001</td></tr> <tr><td>M³-44-11</td><td>32857-001</td></tr> <tr><td>M³-44-15</td><td>32890-001</td></tr> <tr><td>M³-44-21</td><td>33008-001</td></tr> <tr><td>M³-44-22</td><td>33204-001</td></tr> <tr><td>M³-460L-1</td><td>31006-004</td></tr> <tr><td>M³-460L-1A</td><td>31006-006</td></tr> <tr><td>M³-54-1</td><td>32536-001</td></tr> <tr><td>M³-54-2</td><td>33033-001</td></tr> <tr><td>M³X-54-1</td><td>33183-001</td></tr> <tr><td>20-60M³X100</td><td>33006-001</td></tr> <tr><td>M81757/15-1</td><td>32744-001</td></tr> <tr><td>M81757/15-2</td><td>32775-001</td></tr> <tr><td>M81757/15-3</td><td>32764-001</td></tr> <tr><td>M81757/16-1</td><td>32477-001</td></tr> <tr><td>M81757/18-1</td><td>33152-001</td></tr> <tr><td>7-75M³120</td><td>32364-001</td></tr> </tbody> </table> | Type | Part Number | M ³ -28-1 | 33206-001 | M ³ X-33-1 | 33181-001 | M ³ -44-1 | 32663-001 | TM ³ -44-4 | 32794-001 | M ³ -44-7 | 32824-001 | M ³ -44-8 | 32845-001 | M ³ -44-9 | 32848-001 | M ³ -44-11 | 32857-001 | M ³ -44-15 | 32890-001 | M ³ -44-21 | 33008-001 | M ³ -44-22 | 33204-001 | M ³ -460L-1 | 31006-004 | M ³ -460L-1A | 31006-006 | M ³ -54-1 | 32536-001 | M ³ -54-2 | 33033-001 | M ³ X-54-1 | 33183-001 | 20-60M ³ X100 | 33006-001 | M81757/15-1 | 32744-001 | M81757/15-2 | 32775-001 | M81757/15-3 | 32764-001 | M81757/16-1 | 32477-001 | M81757/18-1 | 33152-001 | 7-75M ³ 120 | 32364-001 | Nickel Cadmium Aircraft Battery | Marathon norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-08 | CCS-857 | 31.03.2010 |
| Type | Part Number | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -28-1 | 33206-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ X-33-1 | 33181-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-1 | 32663-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TM ³ -44-4 | 32794-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-7 | 32824-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-8 | 32845-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-9 | 32848-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-11 | 32857-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-15 | 32890-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-21 | 33008-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -44-22 | 33204-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -460L-1 | 31006-004 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -460L-1A | 31006-006 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -54-1 | 32536-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ -54-2 | 33033-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M ³ X-54-1 | 33183-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 20-60M ³ X100 | 33006-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M81757/15-1 | 32744-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M81757/15-2 | 32775-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M81757/15-3 | 32764-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M81757/16-1 | 32477-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| M81757/18-1 | 33152-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7-75M ³ 120 | 32364-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | 32794-001 | Micro Maintenance Nickel Cadmium Aircraft Battery | Marathon Norco Aerospace | Inspection/Test Repair Overhaul Reassembly Modification | 24-34-10 | CCS-857 | 04.04.2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | 30-0909-1, 30-0909-101, 30-0909-103, 30-0909-107, 30-0909-201, 30-0909-203, 30-0909-207, | Aircraft Tail Position Flashtube light | Grimes Aerospace | Inspection/Test Repair (*) Overhaul Reassembly Modification (* repair of connector added only. Other repairs are excluded) | 33-40-38 | CCS-857 | 13.05.2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | Model No: 4025CH1, P/N: 023964-000 | Nickel Cadmium Battery | SAFT | Inspection/Test Repair Overhaul Reassembly Modification | 24-32-02 | CCS-857 | 28.05.2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | 915F212-4, 915F212-5, 915F212-6, 915F212-7, 9 15F212-8 | Generator Control Unit | Hamilton Sunstrand | Inspection/Test | 24-23-30 | CCS-857 | Suspend | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | 948F458-1, 948F458-2, 948F458-3, 948F458-4, 948F458-5 | Generator Control Unit | Hamilton Sunstrand | Inspection/Test | 24-20-01 | CCS-857 | Suspend | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C5 | 1656-6 | Aircraft Batteries | SAFT | Inspection/Test Repair Overhaul Reassembly Modification | 24-31-19 | CCS-857 | 02.07.2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| C6 | S-9100 | Life Preserver Model AV-10, TYPE A | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-178 | CCS-3266 | 27.10.2008 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|---|--------------------------------|---|---|--|---------------------------------|
| C6 | S-10000-() | Life Preserver Model ILV-20 | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-192 | CCS-3266 | 27.10.2008 |
| C6 | S-1200 | Life Preserver Model AV-2A,TYPE A | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-24 | CCS-3266 | 27.10.2008 |
| C6 | S-3100 S-3100-1 | Life Preserver Model AV-12A,TYPE A | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-43 | CCS-3266 | 27.10.2008 |
| C6 | S-12000-() | Life Vest AV-40 | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-191 | CCS-3266 | 27.10.2008 |
| C6 | S-21000-() | Life Preserver Model AV-35 | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-200 | CCS-3266 | 27.10.2008 |
| C6 | S-11000-() | Life Preserver Model AV-35 | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-190 | CCS-3266 | 27.10.2008 |
| C6 | S-51XXX-() | Life Preserver Model AV-35 | Switlik Parachute Company | Inspection/Test Repair Overhaul Reassembly Modification | 25-61-07 | CCS-3266 | 27.10.2008 |
| C6 | RPS1-B & 2013-1A | Batthey Power Supply | Radiant Power Corp. | Inspection/Test | 25-60-03 | CCS-857 | 09.03.2009 |
| C6 | BPS7-2 (Boeing SCD S283T014- 2) & BPS7-3 (Boeing SCD S283T014- 3) | Battery Power Supply | Radiant Power Corp. | Inspection/Test | 25-65-02 | CCS-857 | 02.04.2009 |
| C6 | P0723E105P & VARIANTS P0723E109P & VARIANTS P0723E129P & VARIANTS | Adult/Child Preserver Model KSE-35L8 | Eastern Aero Marine | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-12 | CCS-3266 | 09.07.2009 |
| C6 | P0640-101 and Variants, P0640-103 and Variants, P0640-105 and Variants, P0640-109 and Variants, P0640-111 and Variants, P0640-113 and Variants, P0640-115 and Variants, P0640-117 and Variants | Infant Life Preserver Model IN-V20L8 | Eastern Aero Marine | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-15 | CCS-3266 | 09.07.2009 |

myTECHNIC KOMPONENT BAKIMI KABİLİYETİ LİSTESİ

myTECHNIC COMPONENT MAINTENANCE CAPABILITY LIST

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|--|--------------------------------|---|---|--|---------------------------------|
| C6 | P01074-1XX | Adult/Child life Preserver and container | Eastern Aero Marine | Inspection/Test Repair Overhaul Reassembly Modification | 25-60-30 | CCS-3266 | 27.10.2009 |
| C6 | D29982-103 D29982-107 D29982-109 D29982-111 D29982-113 D29982-119 D29982-121 D29982-123 D29982-125 D29982-127 | Forward passenger/service door evacuation slide assy | Air Cruisers | Inspection/Test Overhaul Reassembly Modification | 25-60-48 | CCS-3266 | 18.12.2009 |
| C6 | Model FV-35E & F (-100, -200, -400 & -500 Series) | Flotation Vest | Hoover Industries | Inspection/Test Overhaul Reassembly Modification | 25-60-06 | CCS-3266 | 28.12.2009 |
| C6 | S-61XXX-() | Life preserver model AV-35 | Switlik Parachute Company | Inspection/Test Overhaul Reassembly Modification Repair | 25-61-08 | CCS-3266 | 28.12.2009 |
| C6 | S-10002-() Series | Life preserver model ILV-20 | Switlik Parachute Company | Inspection/Test Overhaul Reassembly Modification Repair | 25-61-17 | CCS-3266 | 28.12.2009 |
| C6 | P0723-101, P0723-103, P0723-105, P0723-107, P0723-109, P0723-111, P0723-113, P0723-115, P0723-117, P0723-119, P0723-121, P0723-123, P0723-125, P0723-127, P0723-201, P0723-203, P0723-205, P0723-301, P0723-303, P0723-401, P0723-403, P0723-405, P0723-501, P0723-503, P0723-601 | Adult/child life preserver | EAM | Inspection/Test Overhaul Modification Reassembly | 25-60-7 | CCS-3266 | 14.01.2010 |
| C6 | D31591-448, D31591-449, D31591-450, D31591-451, D31591-452, D31591-453, D31591-454, D31591-458, D31591-459, D31591-460, D31591-461, D31591-462, D31591-463, D31591-464, D31591-474, D31591-475, D31591-476, D31591-477, D31591-478, D31591-479, D31591-480, D31591-487, D31591-488, D31591-489 | Forward Door Lightweight Evacuation Slide | Air Cruisers | (*) Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope) | 25-60-59 | CCS-3266 | 15.01.2010 |
| C6 | D29985-103, D29985-107 D29985-109, D29985-111 | Aft Service Door Evacuation Slide | Air Cruisers | (*) Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope) | 25-60-50 | CCS-3266 | 15.01.2010 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|---|--------------------------------|--|---|--|---------------------------------|
| C6 | D29984-103, D29984-109, D29984-113, D29984-119, D29984-211, D29984-213 | Cone Emergency Exit Evacuation Slide | Air Cruisers | (*Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope | 25-60-49 | CCS-3266 | 15.01.2010 |
| C6 | D30664-101, D30664-103, D30664-105, D30664-107, D30664-109, D30664-305, D30664-307, D30664-309, D30664-311, D30665-101, D30665-103, D30665-105, D30665-107, D30665-109, D30665-305, D30665-307, D30665-309, D30665-311 | Evacuation Slide / Raft | Air Cruisers / Aerazur | (* Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope | 25-61-20 | CCS-3266 | 25.01.2010 |
| C6 | D31865-101 (LH), D31865-103 (LH), D31865-105 (LH), D31865-107 (LH), D31865-109 (LH), D31865-111 (LH), D31865-209 (LH), D31865-102 (RH), D31865-104 (RH), D31865-106 (RH), D31865-108 (RH), D31865-110 (RH), D31865-112 (RH), D31865-210 (RH) | Dual Lane off-wing ramp/slide | Air Cruisers/Aerazur | (* Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope | 25-60-58 | CCS-3266 | 26.01.2010 |
| C6 | 61621-469 (BOEING 10- 61323-469) | Aft Door Evacuation Slide | Air Cruisers | (* Inspection / Test Overhaul Modification Reassembly (* Hydrostatic Test is out of scope | 25-66-07 | CCS-3266 | 26.01.2010 |
| C6 | P/N FV-35 Series | Flotation vest | Hoover Industries | Inspection/Test Reassembly, Modification, Overhaul | 25-60-02 | CCS-3266 | 27.04.2010 |
| C6 | P/N 63600 series | AC2000 Life Preserver | Air Cruisers | Inspection/Test Reassembly, Modification, Overhaul | 25-64-02 | CCS-3266 | 27.04.2010 |
| C6 | D31354-425, D31354-426, D31354-429, D31354-433, D31354-434, D31354-435, D31354-437, D31354-438, D31354-439, D31354-442, D31354-443, D31354-447 | Aircraft Evacuation Slide | Air Cruisers | Inspection/Test Reassembly, Modification, Overhaul (* Hydrostatic Test is out of scope | 25-60-54 | CCS-3266 | 27.04.2010 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|----------------------------------|--------------------------------|---|---|--|---------------------------------|
| C6 | A29785-103-1-21, A29785-104-1-21, A29785-105-1-21, A29785-106-1-21, A29785-107-1-21, A29785-108-1-21, A29785-109-1-21, A29785-110-1-21, A29785-105-1-22, A29785-106-1-22, A29785-107-1-22, A29785-108-1-22, A29785-109-1-22, A29785-110-1-22, A29785-105-1-33, A29785-106-1-33, A29785-107-1-33, A29785-108-1-33, A29785-109-1-33, A29785-110-1-33, A29786-105-1-21, A29786-106-1-21, A29786-107-1-21, A29786-108-1-21, A29786-109-1-21, A29786-110-1-21, A29786-111-1-21, A29786-112-1-21, A29786-107-1-22, A29786-108-1-22, A29786-109-1-22, A29786-110-1-22, A29786-111-1-22, A29786-112-1-22, A29786-107-1-33, A29786-108-1-33, A29786-109-1-33, A29786-110-1-33, A29786-111-1-33, A29786-112-1-33, A29784-103-1-21, A29784-104-1-21, A29784-105-1-21, A29784-106-1-21, A29784-107-1-21, A29784-108-1-21, A29784-105-1-22, A29784-106-1-22, A29784-107-1-22, A29784-108-1-22, A29784-105-1-33, A29784-106-1-33, A29784-107-1-33, A29784-108-1-33 | A300 Evacuation Slide | Air Cruisers | Inspection/Test Reassembly Modification Overhaul <i>(Reservoir & valve assy maintenance will be outsourced)</i> | 25-61-11 | CCS-3266 | Suspended |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|-------------------------------------|--------------------------------|---|---|--|---------------------------------|
| C6 | A30466-101-1-21, A30466-102-1-21, A30466-103-1-21, A30466-104-1-21, A30466-101-1-22, A30466-102-1-22, A30466-103-1-22, A30466-104-1-22, A30466-101-1-31, A30466-102-1-31, A30466-103-1-31, A30466-104-1-31, A30466-101-1-33, A30466-102-1-33, A30466-103-1-33, A30466-104-1-33, A30476-101-1-21, A30476-102-1-21, A30476-103-1-21, A30476-104-1-21, A30476-101-1-22, A30476-102-1-22, A30476-103-1-22, A30476-104-1-22, A30476-101-1-31, A30476-102-1-31, A30476-103-1-31, A30476-104-1-31, A30476-101-1-33, A30476-102-1-33, A30476-103-1-33, A30476-104-1-33, D30457-103, D30457-104, D30457-105, D30457-106, D30457-107, D30457-108, D30457-109, D30457-110, D30457-111, D30457-112, D30457-113, D30457-114, D30457-115, D30457-116, D30457-117, D30457-118, D30477-103, D30477-104, D30477-105, D30477-106, D30477-107, D30477-108, D30477-109, D30477-110, D30477-111, D30477-112, D30477-113, D30477-114, D30477-115, D30477-116, D30477-117, D30477-118 | A300 Slide/Raft Evacuation Slide | Air Cruisers | Inspection/Test Reassembly Modification Overhaul <i>(Reservoir & valve assy maintenance will be outsourced)</i> | 25-60-49 | CCS-3266 | Suspend |
| C6 | 8101-01-4000, 8101-01-4000-1, 8101-01-4000B, 8101-01-4000B1, 8101-01-4000C, 8101-01-4000C1 | Oven Control Module | SELL | Inspection/Test Repair Reassembly Modification Overhaul | 25-36-06 | CCS-857 | Suspend |
| C6 | CRANE ELDEC P/N: 8- 930-03, 8-930-03 MOD A, BOEING P/N: S282T003-3 | Battery Charger | CRANE ELDEC | Inspection/Test Reassembly Modification Overhaul | 24-31-06 | CCS-857 | 06.07.2010 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|---|------------------------------------|---|---|--|---------------------------------|
| C6 | D31041-140, -147 (BOEING P/N: S416N202-40, -47), D31041-139, -146 (BOEING P/N: S416N202-39, -46), | 757 Aircraft Slide System | Air Cruisers | Inspection/Test Reassembly Modification Overhaul (Reservoir & Valve Assy Maintenance will be outsourced) | 25-66-03 | CCS-3266 | Suspend |
| C6 | D30546-101, D30546- 109, D30546-205, D30545-101, D30546- 203, D30546-103, D30546-201, D30546- 207, D30545-103, D30545-207, D30546- 105, D30546-203, D30546-209, D30545- 107, D30545-201, D30546-107 | FWD/AFT/MID Door Dual Lane Slide/Raft Evacuation Slide | Air Cruisers | Inspection/Test Reassembly Modification Overhaul (Reservoir & Valve Assy Maintenance will be outsourced) | 25-61-17 | CCS-3266 | Suspend |
| C6 | D30658-114, -117, -120, -123, -314, -317, -320, - 323, -333, (BOEING P/Ns: S416N202-3014, - 3017, -3020, -3023, - 3314, -3317, -3320, - 3323, -3333), D30655- 114, -117, -120, -123, - 133 (BOEING P/Ns: S416N202-1014, -1017, - 1020, -1023, -1033) | 757 A/C single lane slide/raft system door 2 LH/RH | Air Cruisers | Inspection/Test Reassembly Modification Overhaul (Reservoir & Valve Assy Maintenance will be outsourced) | 25-61-27 | CCS-3266 | Suspend |
| C6 | DOOR 4 L.H. ACC 61570-127, -327 (BOEING P/N: S416N202-3027, -3327) 61571-127 (BOEING P/N: S416N202-1027), DOOR 4 R.H. ACC 61570-128, -328 (BOEING P/N: S416N202-3028, -3328) 61571-128 (BOEING P/N: S416N202-1028) | High Gross Weight Aircraft Evacuation slide/Raft System | Air Cruisers | Inspection/Test Reassembly Modification Overhaul (Reservoir & Valve Assy Maintenance will be outsourced) | 25-61-30 | CCS-3266 | Suspend |
| C6 | D30657-113, -116, -119, -122, -313, -316, -319, - 322, -331 (BOEING P/N: S416N202-3013, 3016, 3019, 3022, 3313, 3316, 3319, 3322, 3331), D30654-113, -116, -119, -122, -131 (BOEING P/N: S416N202-1013, 1016, 1019, 1022, 1031) | 757 Aircraft single Lane Slide/Raft system and assembly | Air Cruisers | Inspection/Test Reassembly Modification Overhaul (Reservoir & Valve Assy Maintenance will be outsourced) | 25-61-26 | CCS-3266 | Suspend |
| C6 | D213443 Series D213444 (Serial Numbers L750000 and subsequent and C700000 through C749999 only) | AC-2F and AC-2CF Life Preserver | Air Cruisers | Inspection/Test Reassembly Modification Overhaul | 25-64-03 | CCS-3266 | Suspend |
| C7 | 968214-1 968214-2 968214-3 968214-4 968214-5 968214-6 968214-7 968214-8 968214-9 968214-10 968214-11 968214-12 968214-13 968214-14 968214-15 968214-17 | Pressure Relief Valve Assembly | Allied-Signal Aerospace Company | Inspection / Test Repair Modification Reassembly | 49-31-09 | CCS-998 | 24.06.2008 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|--|--------------------------------|---|---|--|---------------------------------|
| C7 | 21SN41-42 21SN41-52 21SN41-84 | Pressure Switch | Eaton | Inspection/Test Repair Modification Reassembly | 80-21-03 | CCS-998 | 19.12.2008 |
| C7 | 5930645-1, 5930645-501, 5930645-503, 5930645-505, 5930645-507, 5930645-509, 5930645-511, SR09710029-11, SR09710029-13, SR09710029-3, SR09710029-5, SR09710029-7, SR09710029-9 | Engine Nose Section Cowling Assembly | Boeing | Inspection/Test | 71-10-14 | CCS-2681 | 23.02.2009 |
| C7 | 310A020-1, 310A1020-19, 310A1020-3 | CFM56 Engine Mount Components | Boeing | Inspection/Test Reassembly Overhaul Modification | 71-21-13 | CS-2681 | 21.08.2009 |
| C7 | 5938050- 1/501/503/505/507 | Thrust Reverse Assembly | Boeing | Inspection/Test Modification | 78-30-10 | CCS-998 | 04.09.2009 |
| C7 | 405FW504-B | Solid state proximity switch PC assembly | Honeywell | Inspection/Test Repair Reassembly Overhaul Modification | 78-34-01 | CCS-857 | 13.10.2009 |
| C7 | 5930649-1, 5930649-2, 5930649-501, 5930649-502, 5930649-503, 5930649-504, 5930649-505, 5930649-506, 5930649-507, 5930649-508 | Upper Cowl Assembly | BOEING | Inspection/Test Repair (references correspond with the item numbers in Part 1) | 71-10-11 | CCS-2681 | 27.10.2009 |
| C8 | 69-62790-2 | Leading Edge Flap and Slat Position Indicator Unit Assembly | Boeing | Inspection/Test Repair Reassembly Overhaul Modification | 27-56-40 | CCS-857 | 28.10.2008 |
| C8 | 8-060-02 (Boeing P/N: 10-61226-211), 8-060-07 (Boeing P/N: 10-61226- 213), 8-060-10 | Solid state proximity switch PC assembly | Crane Eldec Corporation | Inspection/Test Repair Reassembly Overhaul Modification | 27-09-01 | CCS-857 | 13.10.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|----------------------------------|--------------------------------|--|---|--|---------------------------------|
| C8 | 5922500-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -517, -518, -519, -520, -521, -522, -523, -524, -525, -526, -527, -528, 5922532-1, -2, -501, -502, -503, -504, 5922532-505, -506, -507, -508, -509, -510, -513, -514, 5922533-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -515, -516, 5922534-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -515, -516, -517, -518, -519, -520, -521, -522, 5922535-1, -2, -501, -502, -505, -506, -507, -508, 5937415-1, -2, -501, -502, -503, -504, -505, -506, -507, -508, -509, -510, -511, -512, -513, -514, -515, -516, -517, -518, 5937563-1, -2, -501, -502, -503, -504, -505, -506, -507, -508 | Wing Slat Assembly | BOEING | Inspection/Test | 27-80-1 | CCS-2681 | 03.11.2009 |
| C8 | 65-44851-3/-4/-5/-6/-7/-10/-12/-13/-14 | Ground Spoiler locking Actuator | BOEING | Inspection/Test Modification | 27-60-32 | CCS-998 | 16.11.2009 |
| C9 | 716-663 716-663-1 716-664 716-664-1 716-667 716-667-1 716-668 716-668-1 | Fuel Indicator | Intertechnique | Inspection/Test Reassembly Modification | 28-42-26 | CCS-857 | 23.06.2008 |
| C9 | 2S2542 | Valve – Swing check | CRISSAIR | Inspection/Test Repair Ovehaul Reassembly Modification | 28-20-02 | CCS-1864 | 26.10.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|-------------------------------------|-----------------------------------|---|---|--|---------------------------------|
| C12 | 90G118-2 | Pressure Switch | Custom Component Switches, Inc | Inspection / Test Repair Modification Reassembly Overhaul | 29-12-04 | CCS-998 | 27.10.2008 |
| C12 | 69-54784-1 69-69882-1 69-69882-2 69-69882-3 69-69882-4 69-69882-5 69-69882-6 | Swivel Assembly | Boeing | Inspection / Test Repair Modification Reassembly Overhaul | 29-09-21 | CCS-998 | 09.07.2009 |
| C14 | 2606802-3 2606802-4 2606802-5 | Main Brake Assembly | Allied signal | Inspection / Test *Repair Modification Reassembly Overhaul *: Repair leaking fluid passage plugs in piston housing(Repair #2) & replacing of damaged torque arm bearings (Repair #5) are out of the scope. | 32-42-02 | SUSPEND | 16.11.2009 |
| C14 | 3-1531 3-1531-1 3-1531-2 3-1531-3 | Nose Landing Gear Wheel Assembly | Goodrich | Inspection / Test Repair Overhaul Modification Reassembly | 32-41-13 | CCS-998 | 27.10.2008 |
| C14 | 2607825-1 2607825-2 | Nose Wheel Assembly | Honeywell | Inspection / Test Repair Overhaul Modification Reassembly | 32-40-10 | CCS-998 | 02.12.2008 |
| C14 | 2609801-1 | Main Wheel Assembly | Honeywell | Inspection / Test Repair Overhaul Modification Reassembly | 32-40-11 | CCS-998 | 02.12.2008 |
| C14 | 2606671-1 2606671-2 2606671-3 | Main Wheel Assembly | Honeywell | Inspection / Test Repair Overhaul Modification Reassembly | 32-40-09 | CCS-998 | 02.12.2008 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|---|--------------------------------|---|---|--|---------------------------------|
| C14 | 2612311-1 | Main Wheel Assembly | Honeywell | Inspection / Test Overhaul Modification Reassembly | 32-40-14 | CCS-998 | 02.12.2008 |
| C14 | 2606672-1 2606672-2 2606672-3 2606672-4 | Main Brake Assembly | Honeywell | Inspection / Test Repair Overhaul Modification Reassembly | 32-40-08 | SUSPEND | 02.12.2008 |
| C14 | 2612312-1 | Main Brake Assembly | Honeywell | Inspection / Test Repair Overhaul Modification Reassembly | 32-40-15 | SUSPEND | 02.12.2008 |
| C14 | 3937860-5001 3937860-5002 3937860-5501 3937860-5502 | Main Landing Gear Retract Cylinder Gland Assembly | Douglas Aircraft Company | Inspection / Test Repair Overhaul Modification Reassembly | 32-32-14 | CCS-998 | 24.02.2009 |
| C14 | 286351006 286351006-1 286351007 286351007-1 | Wheel | Messier-Bugatti | Inspection / Test Repair Overhaul Modification Reassembly | 32-41-16 | CCS-998 | 06.03.2009 |
| C14 | 286351005 286351005-1 | Wheel | Messier-Bugatti | Inspection / Test Repair Overhaul Modification Reassembly | 32-41-15 | CCS-998 | 06.03.2009 |
| C14 | 286351004 286351004-1 286351004-2 | Wheel | Messier-Bugatti | Inspection / Test Repair Overhaul Modification Reassembly | 32-41-13 | CCS-998 | 06.03.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|-------------------------------------|--------------------------------|---|---|--|---------------------------------|
| C14 | C21928, C21928-1, 286351003, 286351003-1, 286351003-2, 286351003-3, 286351, 286351003-100, 286351003-101, 286351- 2, 286351002-1, 286351002-2, 286351003-102, 286351003-103, 286351-1, 286351001-1, 286351001-2 | Wheel | Messier-Bugatti | Inspection / Test Repair Overhaul Modification Reassembly | 32-41-12 | CCS-998 | 06.03.2009 |
| C14 | 3-1423-1 (Boeing P/N S160N010- 30) 3-1423-2 (Boeing P/N S160N010- 31) | Nose Landing Gear Wheel Assembly | Goodrich | Inspection/Test Repair Overhaul Modification Reassembly | 32-40-24 | CCS-998 | 11.03.2009 |
| C14 | 3-1422 3-1427 3-1428 | Main Wheel Assembly | Goodrich | Inspection/Test Repair Overhaul Modification Reassembly | 32-40-22 | CCS-998 | 11.03.2009 |
| C14 | 2-1457 2-1457-1 2-1457-2 | Main Landing Gear Brake Assembly | Goodrich | Inspection/Test Repair Overhaul Modification Reassembly | 32-40-26 | SUSPEND | 11.03.2009 |
| C14 | C20211170 C20211171 C20211172 | Wheel | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-44-94 | CCS-998 | 27.04.2009 |
| C14 | C20211100 C20211100-1 C20211100-2 C20211100-3 C20211101 C20211101-1 C20211101-2 C20211101-3 | Wheel | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-44-53 | CCS-998 | 27.04.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|----------------------------------|--------------------------------|---|---|--|---------------------------------|
| C14 | C20211000 C20211000-1 C20211000-2 C20211000-3 C20211000-4 C20211000-5 C20211000-6 C20211001 C20211001-1 C20211001-2 C20211001-3 C20211001-4 C20211001-5 | Wheel | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-41-26 | CCS-998 | 27.04.2009 |
| C14 | C20211150 C20211150-1 C20211150-2 C20211150-3 C20211160 C20211151 C20211151-1 C20211151-2 C20211151-3 C20211161 | Wheel | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-44-54 | CCS-998 | 27.04.2009 |
| C14 | 289021-1001 289021-1002 289021-1201 289021-1202 289021022 289021022-1 289021022-2 28921322 28921322-1 | Wheel | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-41-18 | CCS-998 | 27.04.2009 |
| C14 | C20210500-1, C20210500-2, C20210500-3, C20210500-4, C20210500-5, C20210500-6, C20210500-7, C20210500-8, C20210500-9 | Carbon Brake | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-44-68 | SUSPEND | 29.04.2009 |
| C14 | C20210601, C20210602, C20210603, C20210604, C20210605, C20210606, C20210607, C20210610, | Carbon Brake | Messier-Bugatti | Inspection/Test Repair Overhaul Modification Reassembly | 32-44-69 | SUSPEND | 29.04.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|---|--------------------------------|---|---|--|---------------------------------|
| C14 | 2-1474-5 2-1474-7 (Boeing P/Ns: 10-61819-31 & 10-61819-35) | Main Landing Gear Brake Assembly | Goodrich | Inspection/Test Repair Reassembly Overhaul | 32-40-30 | SUSPEND | 03.07.2009 |
| C14 | 5930583-185, 5930583-186, 5930583-201, 5930583-202, 5930583-203, 5930583-204, 5930583-217, 5930583-218, 5930583-221, 5930583-222, 5930583-237, 5930583-238, 5930583-259, 5930583-260, 5930583-277, 5930583-278, 5930583-281, 5930583-282, 5930583-287, 5930583-288, 5930583-289, 5930583-290, 5930583-293, 5930583-294, 5930583-297, 5930583-298, 5930583-299, 5930583-3, 5930583-300, 5930583-303, 5930583-304, 5930583-305, 5930583-306, 5930583-4 | Main Gear inboard door installation | Boeing | Inspection/Test Reassembly Modification | 32-17-05 | CCS-998 CCS-2681 | 04.09.2009 |
| C14 | 2606801-1, 2606801-2, 2606801-3, 2606801-4 | Main Wheel Assembly and Axle Sleeves | Honeywell | Inspection/Test Repair Reassembly Overhaul Modification | 32-42-06 | CCS-998 | 27.10.2009 |
| C14 | 273A1101-1 | Nose Landing Gear Retract Actuator Assembly | BOEING | Inspection/Test Reassembly Overhaul Modification | 32-33-12 | CCS-998 | 16.11.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|--|---|--------------------------------|--|---|--|---------------------------------|
| C14 | 2608891-1 2608891-1A 2608891-1B 2608891-1C | MD80 Series Main Wheel Assembly | Honeywell | Inspection/Test Reassembly Overhaul Modification Repair (Bearing Cup and Tie-bolt hole radius repairs excluded) | 32-44-01 32-49-01 | CCS-998 | 28.12.2009 |
| C14 | 9550267 9550267-2 9550267-3 9550267-5 9550267-6 9550267-6A 9550267-7 9550267-7A | Nose Wheel | ABSC | Inspection/Test Overhaul Modification Reassembly Repair (Repair#1: Bearing Cup Repair is out of scope. Repair#2: Flame Spray Repair#4: Additional Balance Weight Hole & Self-locking insert is out of scope. Repair#5: Self-locking insert repair is out of scope | 32-46-13 | CCS-998 | 24.12.2009 |
| C14 | 3-1530, 3-1530 OPT2, 3-1530 OPT3, 3-1530 OPT4, 3-1530-1 OPT2, 3-1530-1 OPT3, 3-1530-1 OPT4 | Main Landing Gear Wheel Assembly | Goodrich | Inspection / Test Repair Modification Reassembly Overhaul | 32-41-20 | CCS-998 | 26.01.2010 |
| C14 | 5007897-1, 5007897-2, 5007897-3 | Main Wheel Assembly | ABSC | Inspection/Test (*Repair Reassembly Modification (* Repair no:5-Key Screw Hole Repair is excluded. Bearing Cup Repair is excluded. Disk Drive Key Boss is excluded. Flame Spray Repair of Bearing Bore is excluded. | 32-40-79 | CCS-998 | 15.03.2010 |
| C14 | 3-1484 (BOEING P/N: 10-62174-1) | Main Wheel Assembly | Goodrich | Inspection/Test (*Repair Reassembly Modification Overhaul (* Repair of Wheel Halves to Accept Flexible-type Grese Retainer & Bearing Cup Repair will be outsourced. | 32-45-03 | CCS-998 | Suspend |
| C17 | 617786-2 Series 1 and 2 | Temperature Control Sensor | Honeywell | Inspection / Test Repair Modification Reassembly | 36-13-01 | CCS-857 | 28.10.2008 |
| C18 | 2314M-10 2314M-17 2314M-37 2314M-38 2314M-69 2314M-72 | Windshield Wiper Belleville Washer Arm Assemblies | Rosemount Aerospace Inc. | Inspection/Test Modification Reassembly | 30-44-05 | SUSPEND | 24.06.2008 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|--|--------------------------------|---|---|--|---------------------------------|
| C18 | CG7P0 CG7G0 CG7G0-S CG7G0-10 CG7G0-11 | Smoke Detector | Cerberus Sa | Inspection/Test Repair Reassembly Overhaul Modification | 26-11-15 | CCS-857 | 28.10.2008 |
| C18 | CG7GD1 CG7GE CG7GF CG7GF-10 CG7GFSG CG7PD1 CG7PE CG7PF CG7PF-10 | Smoke Detector | Cerberus Guinard | Inspection/Test Repair Reassembly Overhaul Modification | 26-11-14 | CCS-857 | 28.10.2008 |
| C18 | 17343-116-825F | Aircraft Overheat Detector | Fenwal Safety Systems | Inspection/Test | 26-14-07 | CCS-857 | 24.02.2009 |
| C18 | 680-0021-300 680-0021-310 680-0021-320 | Windshield Temperature Regulator | Electronique Aerospatiale | Inspection / Test Repair Overhaul Reassembly Modification | 30-42-11 | CCS-857 | 02.04.2009 |
| C18 | PU90-401R1 PU90-401R2 PU90-401R3 PU90-401R4 PU90-401S PU90-421R1 PU90-421R2 PU90-421R3 PU90-421R4 PU90-421S PU90-431R1 PU90-431R2 PU90-431R3 PU90-431R4 PU90-431S PU90-441R1 PU90-441R2 PU90-441R3 PU90-441R4 PU90-441S PU90-451R1 PU90-451R2 PU90-451R3 PU90-451R4 PU90-451S PU90-461R1 PU90-461R2 PU90-461R3 PU90-461R4 PU90-461S PU90-499R1 PU90-499R2 PU90-499R3 PU90-499R4 PU90-499S | Smoker Detector Assy | Jamco Corporation | Inspection/Test Repair Overhaul Modification Reassembly | 26-10-02 | CCS-857 | 09.07.2009 |
| C18 | 231-2 | Winshield temperature controller | Primex Aerospace Company | Inspection/Test Repair Overhaul Modification Reassembly | 30-40-02 | CCS-857 | 13.10.2009 |

| Sınıf Kat. Class Rat. | Parça No Part No | Parça Tanımı Part Description | İmalatçı Firma Manufacturer | Bakım Kapsamı Scope of Maintenance | Referans Dok. No Reference Doc. No | *Yetkili Personel Mühür No *Authorised Staff Stamp Number | Onay Tarihi Approval Date |
|--------------------------|---|--|--------------------------------|---|---|--|---------------------------------|
| C18 | 102-00074 | Ice protection low temperature sensor | Norwich Aero | Inspection/Test Modification | 30-00-12 | CCS-857 | 27.10.2009 |
| C18 | 102-00075 | Ice protection high temperature sensor | Norwich Aero | Inspection/Test Modification | 30-00-13 | CCS-857 | 27.10.2009 |
| C18 | 1241X-XXX-XXX 67XXX-XXX-XXX 68021-000-XXX | Midget thermostath unit line | Fenwal Safety Systems | Inspection / Test | 26-14-09 | CCS-857 | 14.12.2009 |
| C18 | KOITO PART NO; 83000-05601, 83000-05601, 83000-05602, BOEING PART NO; 10-61833-1, 10-61833-2, 10-61833-3 | Window Heat Control Unit | KOITO MFG CO LTD | Inspection/Test Repair Reassembly Modification Overhaul | 30-40-03 | CCS-857 | Suspend |
| C18 | PART NO; 83000-05603, 83000-05604, BOEING PART NO; 10-61833-4, 10-61833-6 | Window Heat Control Unit | KOITO MFG CO LTD | Inspection/Test Repair Reassembly Modification Overhaul | 30-40-04 | CCS-857 | Suspend |
| C20 | LM-321-SA15 | Aircraft Engine Mounting System | Lord Aerospace Products | Inspection / Test Repair Reassembly Modification | 54-40-01 | CCS-998 | 27.10.2008 |
| C20 | LM-321-118 LM- 321-118H | Aircraft Engine Mounting System | Lord Corporation | Inspection / Test Repair Modification | 54-40-02 | CCS-998 | 27.10.2008 |
| C20 | LM-321-57 LM-321-58 | Aircraft Engine Mounting System | Lord Corporation | Inspection / Test Repair Modification | 54-40-03 | CCS-998 | 27.10.2008 |
| C20 | A572600000051, A5726000000151, A5726006000051, A5726006000151, A5726006000154, A5726006000251, A5726006000451, A5726006000651, A5726006000751, A5726006000851, A5726006000951, A5726000000052, A5726000000152, A5726006000052, A5726006000152, A5726006000154, A5726006000351, A5726006000551, A5726006000652, A5726006000752, A5726006000852, A5726006000952, A5726006001151 | Wing Tip | AIRBUS S.A.S | Inspection / Test Repair Modification Overhaul | 57-30-11 | CCS-2681 | 22.02.2010 |